

Honda and Acura models with **ALPHA INFLATORS**

The "Alpha" driver-front airbag inflators were the subject of the first Takata airbag inflator recalls starting in 2008, but some of the owners of these vehicles never completed the repairs. Now, because of the time that has passed, the inflators in these vehicles have shown a rupture rate as high as 50%, which can cause serious injuries or death to vehicle occupants.

Following are the vehicles and model years that are part of the "Alpha" inflator recall.



Honda Accord
2001-2002MY



Honda Civic
2001-2002MY



Honda CR-V
2002MY



Honda Odyssey
2002MY



Honda Pilot
2003MY



Acura 3.2TL
2002-2003MY



Acura 3.2CL
2003MY



For complete Honda and Acura recall information,
please visit owners.honda.com/recalls or owners.acura.com/recalls